

Factsheet

Building Services Audit – FNPF Victoria Corner Building

Commercial, Residential and Industrial

Project Title

Building Services Audit – FNPF Victoria Corner Building

Location

Nadi - Fiji

Client

Fiji National Provident Fund

Project Type

Commercial

Year Completed

2010



Project Description

Kramer Ausenco's role:

- Carry out visual inspection of all structural elements and cyclone engineering requirements of this building.
- Comment on the proposed designs (if required) which should comply to the National Building Code of Fiji in particular the reference Australian and New Zealand standards that are called up within this code.

Project Role

- Structural Engineering Services