Factsheet

CNB- Standby Generator Inspection

Commercial, Residential and Industrial

Project Title

CBD- Standby Generator Inspection

Location

Suva - Fiji

Client

Colonial National Bank

Project Type

Commercial

Year Completed

2010





Project Description

Generator assessment - Carry out a physical inspection with the intent to provide a commentary on its present physical condition and provide a professional opinion in brief.

Project Role

• Electrical Engineering Services

