

Factsheet

Ela Beach Hotel Structural Condition Report

Hospitality and Leisure

Project Title

Ela Beach Hotel Structural
Condition Report

Location

Port Moresby, PNG

Client


Steamships – Coral Sea Hotels

Project Type

Hospitality & Leisure

Year Completed

2013



Project Description

Kramer Ausenco provided its client with a Structural Conditioning Report based on careful study of existing structure. Kramer Ausenco's structural engineers carried out extensive investigation on the North and East Wings of the Ela Beach Hotel.

Project Role

- Structural Engineering