

Factsheet

SIG Parliament Building Assessment

Commercial, Residential and Industrial

Project Title

SIG Parliament Building Assessment

Location

Honiara, Solomon Islands

Client

National Parliament of Solomon Islands

Project Type

Commercial

Year Completed

2012



Project Description

Inspection and scoping of the existing National Parliament of Solomon Islands

Kramer Ausenco Role:

- Inspect the existing building, identify and measure the areas required for refurbishment and improvement
- Prepare a scoping report which will entail the item description, condition, refurbishment works required
- Tender invitation, Evaluation, Award & Contract Administration services

Project Role

- Civil Engineers