

Factsheet

Central Bank of the Solomons

Commercial, Residential and Industrial

Project Title

Central Bank of the Solomons

Location

Honiara, Solomon Islands

Client



Central Bank of the Solomons

Project Type

Structural Investigation & Report

Year Completed

2006



Project Description

Kramer Ausenco was commissioned by the Central Bank of the Solomon Islands to undertake a structural review of the bank vault cracks at the head office building in Honiara. This included visual inspection, observations, conclusions and recommendations.

Total Floor Area

280 sqm

Project Role

- Structural Engineers
- Civil Engineers