

Factsheet

Energy Audit of the Bose Levu Vakaturaga Complex

Commercial, Residential and Industrial

Project Title

Detailed Energy Audit Of The BLV Complex

Location

Nasese, Suva, Fiji

Client

Department of Energy

Project Type

Energy Audit

Year Completed

2012



Project Description

The triple storey building is the Bose Levu Vakaturaga Complex which is rented by the Ministry of Finance of Fiji.

Kramer Ausenco (Fiji) Limited were commissioned to conduct a level 2 energy audit of this building.

Total Floor Area

5940 m²

Project Role

- Energy audit for Mechanical, Electrical and Architectural Services