

Factsheet

POSF Vele Rumana

Commercial, Residential and Industrial

Project Title

POSF Vele Rumana

Location

Lae, Morobe, PNG

Client

POSF Board

Project Type

Commercial

Year Completed

2006



Project Description

Client initiated the project to undertake Structural Inspection of the 6 storey building and provide a structural integrity report to include recommendations for any required remedial works.

Kramer Ausenco was commissioned by the Client to undertake structural integrity inspection and report to provide structural assurance that the building is still safe after a fire destroyed an adjacent building. Our structural engineers visited the existing building in Lae City and assessed the building.

Structural Integrity Report was compiled and provided with recommendations to the Client.

Project Role

- Structural Engineers